Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: True Oil LLC
Well Name/Number: Delaney Federal 21-4-4-9H
Location: Lot 3 (NE NW) Section 4 T25N R58E
County: Richland , MT; Field (or Wildcat) Wildcat
At a un
Air Quality
(possible concerns) Long drilling time: No, 25 to 35 days drilling time.
Unusually deep drilling (high horsepower rig): No, triple derrick drilling rig to drill to
19,828'MD/10,283'TVD, single lateral Bakken Formation horizontal well test.
Possible H2S gas production: Possible H2S from the Mississippian Formations.
In/near Class I air quality area: No Class I air quality area in the area of review.
Air quality permit for flaring/venting (if productive Yes, DEQ air quality permit required
<u>under 75-2-211.</u>
Mitigation:
Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements Other:
Comments: No special concerns – using a triple derrick drilling rig to drill to
19,828'MD/10,283'TVD, single lateral Bakken Formation horizontal well test. If there are
existing gas gathering system for natural gas in the area, associated gas can be
gathered or if no gathering system nearby, associated gas can be flared under Board
Rule 36.22.1220.
Water Quality
(possible concerns)
Salt/oil based mud: Yes, oil based invert mud system will be used for drilling the mainhole (75/25 and/or 80/20) and saltwater for drilling the horizontal lateral.
Freshwater and freshwater mud system will be used for drilling the surface hole, rule
36.22.1001.
High water table: No high water table anticipated at this well location.
Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral
drainage adjacent to the southeast corner of this location.
Water well contamination: No, closest water wells are about 3/8 of a mile to the south
southeast, about 5/8 of a mile to the southeast, 5/8 of a mile to the east, about 3/4 of a
mile to the southeast and about 3/4 of a mile to the east from this location. Depth of these
stock and domestic water wells range from 25' to 156'. Surface hole will be drilled with
freshwater and surface casing set to 1950' and cemented to surface, rule 36.22.1001.
Porous/permeable soils: <u>Yes, porous sandy silty soils.</u> Class I stream drainage: <u>No Class I stream drainages in the area of review.</u>
Mitigation:
Lined reserve pit
X Adequate surface casing
Berms/dykes, re-routed drainage
X Closed mud system

X Off-site disposal of liquids (in approved facility) X Other: Lined cuttings pit will be constructed. Liner will be a 12 mil.

Comments: 1950' of surface casing cemented to surface adequate to protect freshwater zones, rule 36.22.1001. Also, fresh water mud systems to be used, rule 36.22.1001. Drilling fluids will be disposed of offsite in an authorized Class II SWD.

Soils/Vegetation/Land Use
(possible concerns)
Steam crossings: No stream crossing anticipated.
High erosion potential: Yes high erosion potential on cut slope, location will have
moderate up to 21.9' and moderate fill, up to 10.7', required.
Loss of soil productivity: No, location will be restored after drilling, if nonproductive. If
productive unused portion of drillsite will be reclaimed.
Unusually large wellsite: Yes, a large wellsite, 430'X370' location size required.
Damage to improvements: Slight, surface use is a cultivated field.
Conflict with existing land use/values: Slight, surface use is a cultivated field.
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Will used existing gravel county road, #142, A short new access road
will be built from the county gravel road into this location, about 411' of new access into
this location. Oil based invert mud will be recycled. Completion fluids will be hauled to a
Class II SWD. Cuttings will be buried in the lined cuttings pit and allowed to dry before
burial. No special concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Nearest residences are about 3/8 of a mile to
the southwest, about 3/4 of a mile to the west southeast, about 1 mile to the northeast
and about 1.875 miles to the northeast from this location.

X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements

Possibility of H2S: <u>Yes, possible H2S from the Mississippian Formations.</u> Size of rig/length of drilling time: Small drilling rig 25 to 35 days drilling time.

Mitigation:

__ Other:____

Comments: Adequate surface casing cemented to surface 1950' and operational BOP (5,000 psig stack, annular and pipe blind rams) should mitigate any problems, rule 36.22.1014.

Wildlife/recreation

(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: None identified.
Conflict with game range/refuge management: No
Threatened or endangered Species: Species identified as threatened or endangered
are the Pallid Sturgeon, Interior Least Tern, Whooping Crane and Piping Plover.
Candidate species are the Greater Sage Grouse and the Sprague's Pipit. NH tracker
website for this Township and Range lists three (3) species of concern:
Whooping Crane, Northern Redbelly Dace and Iowa Darter.
<u></u>
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Private surface cultivated land. There maybe species of
concern that maybe impacted by this wellsite. We ask the operator to consult
with the surface owner as to what he would like done, if a species of concern is
discovered at this location. The Board of Oil & Gas has no jurisdiction over
private surface lands.
private surface failus.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites: None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other:
Comments: Private surface cultivated land There maybe possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We
ask the operator to consult with the surface owner as to his desires to preserve
these sites or not, if they are found during construction of the wellsite. The Board
of Oil & Gas has no jurisdiction over private surface lands.
of Oil & das has no junsalction over private surface lands.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: No concerns. Wildcat well single lateral Bakken Formation well test
19 828'MD/10 283'TVD

Remarks or Special Concerns for this site

Well is a 19,828'MD/10,283'TVD, single lateral Bakken Formation horizontal well test.

Summary: Evaluation of Impacts and Cumulative effects

No long term impacts expected. Some short term impacts will occur, but will be mitigated in time.

I conclude that the approval of the subject Notice of Intent to Drill (does/<u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/<u>does not</u>) require the preparation of an environmental impact statement.

Prepared by (BOGC): \s\Steven Sasaki
(title:) Chief Field Inspector
Date: <u>June 8, 2013</u>
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC
website.
(Name and Agency)
Richland County water wells.
(subject discussed)
June 8, 2013
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES
MONTANA COUNTIES, Richland County
(subject discussed)
June 8, 2013
(date)
Montana Natural Heritage Program Website (FWP)
(Name and Agency)
Heritage State Rank= S1, S2, S3, T25N R58E
(subject discussed)
lung 9, 2012
(date)
Montana Cadastral Website
(Name and Agency)
Surface Ownership and surface use Section 25 T30N R58E
(subject discussed)
June 8, 2013
(date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: